Traversing Lathe Guards

- Machine Type Light to medium centre lathes
- Method of attachment Secures to lathe saddle
- · Manually adjusted to cover work area
- Construction Cast aluminum and 4 mm polycarbonate visors
- Operation Traverses with saddle hinges to allow access to chuck and work area





Model - SL6, SL12 & SL18





