



Order No.		s	e	m = 3d	 g
2460.W106	M 6	10	11,5	18	8
2460.W108	M 8	13	15,0	24	19
2460.W110	M10	16*	18,4	30	30
2460.W112	M12	18*	20,7	36	48
2460.W114	M14	21*	24,2	42	73
2460.W116	M16	24	27,7	48	120
2460.W118	M18	27	31,2	54	170
2460.W120	M20	30	34,6	60	240
2460.W122	M22	34*	39,2	66	390
2460.W124	M24	36	41,5	72	400
2460.W127	M27	41	47,3	81	600
2460.W130	M30	46	53,1	90	850
2460.W136	M36	55	63,5	108	1470
2460.W142	M42	65	75,0	126	2340
2460.W148	M48	75	86,5	144	3600