



Order No.		s	e	m = 1,5d	r	 g
2430.W106	M 6	10	11,5	9	9	5
2430.W108	M 8	13	15,0	12	12	9
2430.W110	M10	16*	18,4	15	15	14
2430.W112	M12	18*	20,7	18	17	20
2430.W114	M14	21*	24,2	21	20	34
2430.W116	M16	24	27,7	24	22	58
2430.W118	M18	27	31,2	27	24	83
2430.W120	M20	30	34,6	30	27	110
2430.W122	M22	34*	39,2	33	30	185
2430.W124	M24	36	41,5	36	32	195
2430.W127	M27	41	47,3	40	36	280
2430.W130	M30	46	53,1	45	41	405
2430.W136	M36	55	63,5	54	50	715
2430.W142	M42	65	75,0	63	58	1170
2430.W148	M48	75	86,5	72	67	1800